

# BUILDER INSIGHT



## Sidewall Venting of Gas Appliances

### Overview

Newer modern gas appliances used for space and water heating are increasingly being installed with sidewall venting as it is easier for builders and equipment installers to implement. Proper care and attention are required in the design and installation of the vents in order to ensure that the exhaust is dissipated away from the building and its occupants.

Combustion gases in traditional gas appliances were vented through the roof. The buoyancy effect of warm gases was relied on to move the exhaust gases up through a chimney flue and out of the building. Gases were quickly dispersed upwards into the atmosphere with few consequences on the building or its occupants.

Today's high efficiency appliances have lower temperature flue gases and must use forced venting systems to ensure proper exhaust gas flow. High efficiency, power vented equipment no longer requires a chimney and can be vented through the wall of a building.

Current Gas and Building Codes allow venting through the sidewall. Sidewall venting is easier for builders and equipment installers to implement saving them time, materials, labour and interior living space (by avoiding flue chases) in both new construction and renovations. These inherent advantages have made sidewall venting increasingly popular in British Columbia and elsewhere in Canada.



*Furnace flue gases from a high efficiency furnace vented through the roof – mostly moisture.*



*Venting should never be placed underneath the building or cold floor areas.*

**Builder Insight** is a series of bulletins and companion videos designed to provide practical information about new and emerging technologies, best practices and current issues in residential construction to Licensed Residential Builders and others in the industry. Produced by BC Housing, this bulletin was prepared by Richard Kadulski Architect in collaboration with industry and research experts.

### Contents

- Overview ..... 1
- How Does Sidewall Venting Differ from Chimney Venting?..... 2
- What Issues Can Arise from Sidewall Venting?..... 3
- Natural Gas and Propane Installation Code (CSA B149.1) ..... 4
- What can be done to avoid problems? ..... 4
- Key Points ..... 5
- More Information..... 5

The Canadian Standards Association (CSA) addresses aspects of natural gas and propane appliance installation (CSA B149.1). However, it does not address the impact of vent gases on the building envelope or those of neighbouring buildings. The BC Building Code is currently silent with respect to the placement of sidewall vents other than requiring compliance to the Gas Code. Some jurisdictions in Canada are beginning to look at the issue, and are considering placing restrictions on the location of the vents.

Other design elements with similarities are covered in the BC Building Code, including:

- Restrictions on the number of unprotected openings in walls close to a property line and spatial separation provisions.
- Location and height of chimneys relative to portions of the building and neighbouring buildings.

### How Does Sidewall Venting Differ from Chimney Venting?

In a traditional rooftop flue, the combustion gases dissipate into the atmosphere. In the case of sidewall vented appliances, the gases are discharged close to the ground, adjacent to the house. The warm, moist gases move up the wall of the house and against any overhangs above. The moisture plume is very visible on a cool day, as the exhaust gases form vapour clouds when they leave the flue.

Since the heating appliance is firing for long periods during cold weather, which generally is associated with high outdoor humidity levels, the vapour cloud can overload the capacity for the adjacent building surfaces to manage all this moisture. Frost and ice buildup can be noticeable in the winter as the plume condenses water on the colder surfaces – such as the siding. Moisture absorption within the building materials will not be as noticeable, but can have a big impact on their durability.

In infill situations and narrow lot subdivisions, the side yards between houses are narrow, limiting air movement. This offers less opportunity for the dissipation of the flue gases or for the drying of moisture accumulating on adjacent surfaces of the house with the appliance, and also the neighbouring house. See photo below. Such buildup is not only an aesthetic concern; it can also compromise the long-term durability and performance of the building.

The main by-products of natural gas combustion are carbon dioxide and moisture. Other by-products include carbon monoxide, nitrous oxides, sulphur dioxide and particulates. For every 10,000 BTU/hr of gas burned, 452 g/hr of moisture is generated. As such, a 50,000 BTU furnace or boiler can put out the equivalent of about 2.5 or more litres of moisture per hour. On a cold day, depending on the heat load and firing time, a furnace and water heater can generate flue gases that are



*In cold climate conditions, vent gas condensation is visible as frost buildup against wall and roof overhang.*



*Moisture from flue gases accumulating on the wall of a heritage building will affect the durability of that building.*



*Sidewall vented appliance retrofitted into an older home blows flue gases against the neighbouring house where it has led to ice buildup.*

equivalent to throwing 30 to 120 litres of water into the air, close to the surface of the house adjacent to the vent. A high efficiency condensing appliance should vent less moisture, but there will nevertheless be significant quantities of moisture in the vented gases.

While dryer and bath fan vents also release a vapour plume adjacent to a house, the extent of their related damage is not as significant. This is likely because the dryer or bath fan operate intermittently, and for a short duration, compared to the gas furnace or boiler.

## What Issues Can Arise from Sidewall Venting?

Improper sidewall venting can have serious unintended consequences that must be recognized and addressed. A number of different elements can be impacted:

- Building envelope
- Attic moisture and mould
- Air quality and health
- Noise

### Building Envelope Damage

As discussed, the moisture generated by the gas combustion in winter can both condense on and be absorbed by building envelope materials, which can lead to damage. In winter, the exterior building envelope materials are already at or nearly at saturation moisture content. With very little drying potential, the additional moisture can impact the building envelope durability. Icing problems on building envelopes due to sidewall venting have been observed on the Prairies and have prompted some authorities in Saskatchewan and Alberta to introduce local requirements for larger spacing requirements between houses with sidewall vents. Minimum distances as great as 8 feet (2.4 m) between a house and property line are proposed.

### Attic Moisture and Mould

The flue gases moving up the house can enter the attic through the soffit vents where they can condense on the framing and underside of the roof sheathing. There have been reports of moisture and mould on the underside of roof sheathing in houses with sidewall vented appliances and also on adjoining houses. Some builders have even reported condensation and mould growth in new houses that are still under construction — where the water vapour from an adjacent home's gas appliance is blown into the attic. Similar problems have been observed in older homes retrofitted with new high efficiency gas furnaces where the venting has been put through the wall rather than keeping it through the roof.

### Air Quality and Health

There are also potential health impacts associated with sidewall venting. Indoor air quality can be negatively affected if there are operable windows near a sidewall vent that are left open when the gas appliance is operating. Similarly, if there is a ventilation air intake in the area, the indoor air quality can be compromised as the combustion gases can be drawn in. Because the gas-fired appliance is often located in the basement or crawlspace, the vent is taken directly out the sidewall of the building. The vent gases are often dispersed near the ground in narrow confined spaces between buildings — a less than ideal situation.

Malfunctioning equipment can produce higher levels of carbon monoxide and other harmful combustion gases that can affect occupant health.

### Noise

Another issue raised by some building officials is that of equipment noise. The fan motors of some power vented equipment can be loud, even when installed according to manufacturer specifications. These noise levels can exceed allowable noise limits set out in municipal by-laws.

## Natural Gas and Propane Installation Code (CSA B149.1)

The Natural Gas and Propane Installation Code (CSA B149.1) focuses on installation requirements for:

- The safe operation of the gas appliance.
- Dispersal of combustion gases, including the separation of vent gases from windows and mechanical air supply for the building.
- Placement of vents to prevent re-entrainment of combustion gases into the building.
- The extent frost or ice can buildup on adjacent property surfaces.

### CSA B149.1 Article 8.14.8 states that a vent shall not terminate:

- › Where it may cause hazardous frost or ice accumulations on adjacent property surfaces.
- › Less than 7 feet (2.1 m) above a paved sidewalk or a paved driveway that is located on public property.
- › Within 6 feet (1.8 m) of a mechanical air-supply inlet to any building.
- › Within 3 feet (900 mm) horizontally of the vertical centerline above the gas service regulator vent outlet to a maximum vertical distance of 15 feet (4.5 m).
- › Less than 1 foot (300 mm) above grade level.
- › Within 12 inches (300 mm) of a window or door that can be opened in any building, of any non-mechanical air-supply inlet to any building, or of the combustion air inlet of any other appliance for gas units up to and including 100,000 BTU/hr (30 kW).
- › Within 3 feet (900 mm) of a window or door that can be opened in any building, of any non-mechanical air-supply inlet to any building, or of the combustion air inlet of any other appliance for gas units exceeding 100,000 BTU/hr (30 kW).

The Gas Code requires that there be a side yard equal to or greater than 4 feet (1.2 m) to the property line. It also requires a means of redirecting the vent plume with a certified fitting such as a “T”, a 90-degree elbow, or termination acceptable to the authority having jurisdiction. The vent termination must be installed in accordance with the manufacturer’s instructions. There are no restrictions on the placement of a sidewall vent relative to an adjoining building if they are separated by 8 feet (2.4 m) or more.

The Gas Code permits the placement of a vent underneath a veranda, porch, or deck if it is fully open on at least two sides underneath the floor. The distance between the top of the vent termination and the underside of the veranda, porch, or deck must be at least 1 foot (0.3 m). However, this is never advisable because it is a location where ice and condensation can build up and lead to structural deterioration. An example of this ice accumulation is evident in the photo on page 2.

## What Can be Done to Avoid Problem?

- Venting combustion gases through the roof is recommended to avoid a number of potential problems associated with sidewall venting. Most sidewall vented equipment can release gas through the roof. Manufacturer’s product literature and installation instructions provide the installer with information, including the maximum allowable length of vent pipe and options for increasing the vent length – usually achieved by increasing the diameter of the vent pipe. In most cases, even a larger vent pipe will still fit within standard wall framing, so special flue chases should not be required.
- When venting through the roof, determine the location of mechanical equipment and placement of venting needs early in the design stage, to minimize problems during construction. Large chases for traditional chimneys and B-vents are not required, but the vent pipes, typically 2 inch (50 mm) to 4 inch (100 mm) in diameter, have to be accommodated within interior walls.

- It may be challenging to find a place to install vents in contemporary open concept floor plans because there are fewer interior walls.
- When sidewall venting must be used, vent terminations should be placed so the vent gases can be dispersed quickly into open areas, away from operable windows and other openings.
- Always ensure that the installation is done in accordance with CSA B149.1 and the manufacturer's installation instructions.
- Never place a vent underneath a cold floor, deck or adjacent to a roof overhang.
- If there are vented soffits above a sidewall vent, the soffit vents should be sealed for 6 feet on either side of the vent. Draw a vertical line above the vent and measure 6 feet on either side of that line. If the roof space is to be vented, ensure that there is adequate venting overall in other portions of the attic.

## Key Points to Remember When Installing Sidewall Venting

- ❑ Don't place sidewall vent terminations near openings or underneath any structure that can obstruct the dissipation of the exhaust gases.
- ❑ Place vent termination in an exposed location where flue gases can dissipate widely – preferably through the roof.
- ❑ Ensure penetrations through the building enclosure maintain the continuity of the air barrier.
- ❑ When sidewall venting cannot be avoided, seal all soffit vents immediately above the vent – even if the soffit is two floors above.

## More Information

- › CSA B149.1, Natural Gas and Propane Installation Code, available at [www.shop.csa.ca](http://www.shop.csa.ca)
- › Vent – Terminal Locations as Related to Air Infiltration and Indoor Air Quality, available at [www.iifiir.org](http://www.iifiir.org)
- › Subscribe to receive Builder Insight bulletins at [www.bchousing.org](http://www.bchousing.org)

### Disclaimer

The greatest care has been taken to confirm the accuracy of this information. The authors, funder and publisher assume no liability for any damage, injury or expense that may be incurred or suffered as a result of the use of this publication including products, building techniques or practices. The views expressed do not necessarily represent those of any individual contributor or BC Housing. It is always advisable to seek specific information on the use of products in any application or detail from manufacturers or suppliers of the products and consultants with appropriate qualifications and experience.

It is acknowledged that many product options exist. Materials and products depicted in figures are shown as examples and do not represent an endorsement of any specific brands or products.

### About BC Housing Research Centre

BC Housing's Research Centre works in collaboration with housing sector partners to foster excellence in residential construction and find innovative solutions for affordable housing in British Columbia. Sharing leading-edge research, advances in building science, and new technologies encourages best practice. The Research Centre identifies and bridges research gaps to address homelessness, housing affordability, social housing challenges and the needs of distinct populations. Mobilizing knowledge and research expertise helps improve the quality of housing and leads to innovation and adoption of new construction techniques, Building Code changes, and enhanced education and training programs. Sign up to receive the latest news and updates from BC Housing's Research Centre at [www.bchousing.org/subscribe](http://www.bchousing.org/subscribe).